

## Number: GZHT90304621

Applicant: SHEEN TIGER TECHNOLOGY CO., LTD. Date: Jul 25, 2012 NO. 61, HSIN TSO RD., PI-LI MI, TOU-NAN CHEN, YUN-LIN HSIEN TAIWAN Attn: JAY SHEN

Sample Description: One (1) piece of submitted sample said to be #20120719 WELLMAX antipenetration midsole in White with Black printing. Standard : EN ISO 20345: 2011 Ref. No. : 20120719 Date Received/Date Test Started : Jul. 20, 2012

Test Result Please Refer To Attached Page(S).

Should you have any query on this report, you may contact at gzfootwear@intertek.com

Authorized By: For Intertek Testing Services Shenzhen Ltd.

Huang Ning, Andy Assistant General Manager

AZ / wynnzhang

Page 1 Of 3

Intertek Testing Services Shenzhen Ltd. Textile & Footwear Division 3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou Economic & Technological Development District, Guangzhou, P.R.C 深圳天祥质量技术服务有限公司纺织鞋类测试部 中国广州经济技术开发区开发大道 235 号恒运大厦 3 楼 Tel: (8620)2232 1668/8396 6868 Fax: (8620)8208 9909 Postcode: 510730



## Test Report

Number: GZHT90304621

Tests Conducted (As Requested By The Applicant)

1 Thickness (Insole) (EN ISO 20344:2011(7.1))

Requirement Pass/Fail 4.3 mm Min. 2.0 mm Pass Expanded Uncertainty: 0.07 mm, With k= 1.96 At 95% Confidence Level. Water Absorption & Desorption (Insole) (EN ISO 20344:2011(7.2)) 2 Requirement Pass/Fail Water Absorption  $93 \text{ mg/cm}^2$ \* Pass Water Desorption 84% Pass Remark: \* = Water Absorption: Min.70 mg/cm<sup>2</sup> Water Desorption: Min.80% Expanded Uncertainty: Water Absorption: 0.10 mg/cm<sup>2</sup>, With k = 1.96 At 95% Confidence Level. Water Desorption: 0.03%, With k= 1.96 At 95% Confidence Level. 3 Abrasion Resistance (Insole) (EN ISO 20344:2011(7.3))

RequirementPass/FailNo More Than Severe Damage\*PassBefore 400 Cycles.\*Pass

Remark: \* = There Shall No More Than Severe Damage Before 400 Cycles.


This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.

AZ / wynnzhang

Page 2 Of 3

Intertek Testing Services Shenzhen Ltd. Textile & Footwear Division 3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou Economic & Technological Development District, Guangzhou, P.R.C 深圳天祥质量技术服务有限公司纺织鞋类测试部 中国广州经济技术开发区开发大道 235 号恒运大厦 3 楼 Tel: (8620)2232 1668/8396 6868 Fax: (8620)8208 9909 Postcode: 510730





Tests Conducted (As Requested By The Applicant)



AZ / wynnzhang

Page 3 Of 3

Intertek Testing Services Shenzhen Ltd. Textile & Footwear Division 3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou Economic & Technological Development District, Guangzhou, P.R.C 深圳天祥质量技术服务有限公司纺织鞋类测试部 中国广州经济技术开发区开发大道 235 号恒运大厦 3 楼 Tel: (8620)2232 1668/8396 6868 Fax: (8620)8208 9909 Postcode: 510730