



Number: GZHT90389606

Date: Sep 30, 2013

Applicant: SHEEN TIGER TECHNOLOGY CO., LTD.
NO. 61, HSIN TSO RD., PI-LI MI,
TOU-NAN CHEN, YUN-LIN HSIEN
TAIWAN
Attn: JAY

Sample Description:

Five (5) pairs of submitted sample said to be R-2011 composite toe cap.
Standard : CSA Z195-09
Ref. No. : 20130923
Size : 6, 8, 10, 12, 14
Country Of Origin : TW
Date Received/Date Test Started : Sep. 26, 2013

Test Result Please Refer To Attached Page(S).

Should you have any query on this report, you may contact at gzfootwear@intertek.com

Authorized By:
For Intertek Testing Services Shenzhen Ltd.
Guangzhou GDD Branch



Huang Ning, Andy
Assistant General Manager

AZ / abbyzeng



Page 1 Of 3

Intertek Testing Services Shenzhen Ltd. Guangzhou GDD Branch
3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou
Economic & Technological Development District, Guangzhou, China
深圳天祥质量技术服务有限公司广州开发区分公司
中国广州经济技术开发区开发大道235号恒运大厦3楼
Tel: (8620)2232 1668 / 8396 6868 Fax: (8620)8222 7490 Postcode:510730



Number: GZHT90389606

Tests Conducted (As Requested By The Applicant)

Toecap Impact Resistance (CSA Z195-09, Modified, 125 Joules)

<u>Size 6</u>	Left	22.3 mm
	Right	22.3 mm
<u>Size 8</u>	Left	23.3 mm
	Right	23.5 mm
<u>Size 10</u>	Left	23.0 mm
	Right	24.3 mm
<u>Size 12</u>	Left	25.2 mm
	Right	23.0 mm
<u>Size 14</u>	Left	25.1 mm
	Right	28.3 mm

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.

AZ / abbyzeng

Page 2 Of 3

Intertek Testing Services Shenzhen Ltd. Guangzhou GDD Branch
3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou
Economic & Technological Development District, Guangzhou, China
深圳天祥质量技术服务有限公司广州开发区分公司
中国广州经济技术开发区开发大道 235 号恒运大厦 3 楼
Tel: (8620)2232 1668 / 8396 6868 Fax: (8620)8222 7490 Postcode:510730



Number: GZHT90389606

Tests Conducted (As Requested By The Applicant)



AZ / abbyzeng

Page 3 Of 3

Intertek Testing Services Shenzhen Ltd. Guangzhou GDD Branch
3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou
Economic & Technological Development District, Guangzhou, China
深圳天祥质量技术服务有限公司广州开发区分公司
中国广州经济技术开发区开发大道 235 号恒运大厦 3 楼
Tel: (8620)2232 1668 / 8396 6868 Fax: (8620)8222 7490 Postcode:510730